




Gut the coil – this one was fried by excess voltage:





An alternative method:

