




1
TAP
THREADS



2
INSERT
BOLT



3
PRESS
OUT

Side Mount Distributor
Bushing removal