


FOR P-AO-20 AND P-AO-21 DISC PLOWS



Form No. 693 004 M1

Replaces 0-3433A


FERGUSON DIVISION

MASSEY-HARRIS-FERGUSON, INC. RACINE, WISCONSIN


71/2 M-3-55-K

www.ntractorclub.com

PRINTED IN W. S.




Ref.		Do	at Mc		Pople on a	D			Req.	
NO.		Pal	rt No	<u>.</u>	Replaces	Description	P-A0-20	P-A0-21	P-A0-98	P-A0-99
						Third Bottom Conversion Kit (Inc. items 1 thru 11, 16, 18 thru 24 and 29, page 5. Items 1 thru 4, page 7.		1		
Di-						All items, page 10)		1		
						26 thru 28, page 9. All items, page 1		_	_	_
	1		127		P-A0-126	Bolt, Plow Special, Disc Hub	10	10	5	5
1	4		432		44-14	Washer, Lock		10	5	5
	>		426		44-003	Nut, Hex	10	10	5	5
2			125		P-A0-121	Disc, Plow (3/16")	2	2	1	1
3	-		126		P-A0-131	Disc, Plow (1/4 Optional w/ 660 125 M1)		2	1	1
4			175 130		P-A0-3821 P-A0-3822	Hub, Disc		2	1	1
5			176		P-A0-3823	Retainer, Grease		2 2	1 1	1
6			309		S-9848	Cone and Roller Assm., Inner, Disc Hub.		2	1	1
	1		173		P-A0-3817	Bracket and Bearing Cup Assembly (Inc.	2	4		1
7	18	-				Bracket not serviced)	2	2	1	1
	1		308		S-9849	Cup, Bearing, Inner (shown in positio		1	1	1
	1		030		S-9846	Cup, Bearing, Outer (shown in positio		1	1	1
8	1		031		S-9845	Cone and Roller Assm., Outer, Disc Hub.	2	2	1	1
9			088		P-A0-3819	Nut, Slotted, Disc Bearing	2	2	1	1
10	-		132		25-05-225 P-A0-3824	Pin, Cotter	2	2 2	1	1
11			133		P-A0-3825	Gasket, Hub Cap	2 2	2	1	1
	1		404		S-10214-J	Pin, Clevis, Bracket to Leg	2	2	_	1
12			086		12-05-88	Pin, Cotter	1	1		-
			415		S-10202-B	Pin, Internal Cotter	1	1	12.2	
13	-	660	118	M91	P-A0-780	Leg Assembly, Stand	1	1	_	
14		660	115	M91	P-A0-790	Bracket Assembly, Stand	1	1	- C-	-
15	1		223 864		AO-7805-D 62-011-175	Shaft, Cross Bolt Carr Seranor Bracket to	1	1	-	
		000	001	АТ	02-011-175	Bolt, Carr., Scraper Bracket to Bracket Assembly	2	2	1	1
16		354	433	X1	62-14	Washer, Lock	2	2	1	1
	L		427		62-003	Nut, Hex	2	2	î	1
		660	538	M1	AO-9588-D	Clamp, Cross Shaft U-Bolt (Not Illust.)	2		_	_
		195	451	Ml	S-10400	U-Bolt, Cross Shaft	2	2	-	-
17			433		62-14	Washer, Lock	4	4		- 5
	L		427		62-003	Nut, Hex	4	4	-	-
18			200		P-A0-226	Bracket, Scraper	2	2	1	1
19			135		P-A0-227-A	Block, Scraper Positioning	2	2	1	1
20 21			165 129		P-A0-220	Scraper Assembly, Disc	2	2	1	1
21	-		060		P-A0-228 S-10350	Clamp, Scraper Shank	2 t 2	2 2	1 1	1
22			433		62-14	Eyebolt, Scraper Shank, Shank to Bracke Washer, Lock	2	2	1	1
	L		427		62-003	Nut, Hex	2	2	î	î
	1		138		P-A0-3841	Bolt, Sq. Hd., Bracket to Front Rail to				
		660	139	M1	P-A0-3842	Stand Bracket	0	2		
23						bottoms are used	2	-	m - 1	_
		660	137	Ml	P-A0-3840	Bolt, Sq. Hd., Bracket to Second Rail	0			
	1	353	443	v	100-14	- When Third Bottom is used	4	2 4	2 2	2 2
			055		S-33841	Washer, Lock	4	4	2	2
24	•		057		S-353063	Plug, Pipe	2	2	1	1
25			122		P-A0-7812	Cap, Beam End	2	2	-	-
	1		123		P-A0-7813	Hook, Bolt, Front (Not Illustrated)	1	1	_	
		660	124	M1	P-A0-7824	Hook, Bolt, Rear	1	1	-	-
26	1	353	757	X1	44-104	Washer, Flat	1	1	2	
			432		44-14	Washer, Lock	1	1	- 1	-
	5		426		44-003	Nut, Hex	1	1	= 1-2	-
27			169		P-A0-794	Cover Assembly, Hole	4	4	·	
	(172		P-A0-798	Washer, Hole Cover (shown in position).	4	4	7 - 1	-
28 29			177 189		P-A0-7800 P-A0-141	Frame Assembly Disc, Plow (26" cutout)	1 2	1 2	1	1
23		000	100	III A	1-10-141	DISC, FIOW (20 Catolat)	4	4		1



www.ntractorclub.com


Ref.	Part No.	<u>.</u>	Replaces	Description	P-A0-20	No. F P-AO-21	Req. P-AO-98	P-A0-99
	353 895 X	(1	62-001-825	Bolt, Hex. Hd., Third Beam to Plow	_	_	2	2
1	353 433 X	(1	62-14	Washer, Lock		-	2	2
70	353 427 X		62-003	Nut, Hex	-	7-6	2	2
2	660 168 M	11	P-A0-797	Bushing	- 11	-	4	4
	f 660 139 M	(1	P-A0-3842	Bolt, Sq. Hd., Bracket to Rear Rail to	MAN L			
	000 133 11		F-R0-3012	Furrow Wheel Bracket, when Third Botto	The same of the sa			
	660 137 M	1 1	P-A0-3840	Bolt, Sq. Hd., Bracket to Second Rail,	2	-	-	-
	000 137 M	41	F-A0-3040	when Third Bottom is used	2	2	2	2
3	660 136 M	11	P-A0-3839	Bolt, Sq. Hd., Bracket to Rear Rail to Furrow Wheel Bracket, when Third Botto	am .			
	ACCOUNTAGE OF			is used		2	7000	
	252 764 V	71	100 104		2	2	2	2
	353 764 X		100-104	Washer, Flat				
	353 443 X		100-14	Washer, Lock	2	2	2	2
	(195 055 M	M1	S-33841	Nut, Special Hex	2	2	2	2
4	660 197 M	M91	P-A0-7803	Beam Assembly, Third Disc	-	-	1	1
	660 234 M	r1	P-A0-9501	H Bolt Furrow Spring to Ayle	1	1000	100	
				U Bolt, Furrow Spring to Axle		1		1
5	660 149 M		P-A0-9502	U Bolt, Furrow Spring to Axle	-		-	
	353 772 X		44-204	Washer, Flat	2	2		2
	\ 353 426 X	X1	44-003	Nut, Hex	2	2	-	2
6	660 146 M	M1	P-A0-7001	Spring, Furrow Wheel, Short	1	1	-	1
7	660 147 M	M1	P-A0-7002	Spring, Furrow Wheel, Middle	1	1	-	1
8	660 145 M	W1	P-A0-7000	Spring, Furrow Wheel, Long	1	1	-	1
9	660 141 M	w1	P-A0-6621-A	Link, Spring	2	2	_	2
						0		0
- 10	195 400 M		S-10214-E	Pin, Clevis, Links to Axle	2	2	_	2
10	(354 058 X	X1	12-05-88	Pin, Cotter	2	2	-	2
20.00	f 660 231 M	M1	P-A0-6620	Bracket, Furrow Wheel	1	- 2	-	_
11	660 090 M	M1	P-A0-6625	Bracket, Furrow Wheel	-	1		1
12	660 142 M	M1	P-A0-6624	Collar, Furrow Wheel Axle	1	1	-	1
13	353 453 X	X1	44-125-225	Pin, Groove	1	1	-	1
14	13 222 X	X	12-107	Fitting, Grease, Furrow Wheel Bracket.	1	1	_	1
15	660 233 M	M1	P-A0-7400	Axle, Furrow Wheel	1	7		7
15	l 660 148 M	M1	P-A0-7406	Axle, Furrow Wheel		1	->:	1
	ſ 660 144 M	M1	P-A0-6629-A	Bolt, Hex. Hd., Adjustment for Axle	1	2	-	2
16	353 428 X	X1	44-1003	Nut. Hex	1	2	-	2
	353 432 X		44-14	Washer, Lock (Not Illustrated)	1	-		
17	180 009 M	MI	то-1139	Cap, Hub	1	1	-	-
	(050 000 -		75 010	Wat olds was Barries and St.	2	,		
18	353 928 X		75-013	Nut, Sltd., Hex., Furrow Wheel Spindle	1	1	_	-
10	[354 068 X	X1	16-05-125	Pin, Cotter	1	1	-	
19	180 010 M	M1	то-1195	Washer, Hub Bearing Retainer	1	1	-	
20	150 669 1	wa.	c 0842	Cone and Poller Assambly Outer Furnor				
20	150 662 M	m I	S-9842	Cone and Roller Assembly, Outer, Furrow Wheel	1	1		-
					-1.25	Mr.		
21	353 696 X	X1	44-101-75	Screw, Cap, Disc to Wheel and Bearing Assembly	8	8	_	_
					- 1			



www.ntractorclub.com

Ref.	Par	t No.	Replaces	Description	P-A0-20	No. F		P-A0-99
00 1	660	151 M1	P-A0-6611	Disc, Furrow Wheel, 18"	1	1	_	-17
22		188 M1	P-A0-6614	Disc, Furrow Wheel, 20"	1	1	-	-
23	660	152 M91	P-A0-6613-A	Wheel and Bearing Assembly, Furrow		N DC		
				(Inc. Wheel not serviced)	1	1	-	-
		127 M1	S-9843	Cup, Bearing, Outer (shown in position		-1	-	2.7
		420 M1	S-10169	Ring, Snap (shown in position)	1	1	-	-
	195	182 M1	S-9838	Cup, Bearing, Inner (shown in position	1) 1	1	-	-
24	195	181 M1	S-9839	Cone and Roller Assembly, Inner, Furrow	1	1		
				Wheel	1	1	_	- 69
25	180	008 M1	TO-1190	Seal, Hub Dust	1	1	-	-
26	660	154 Ml	P-A0-7403	Spindle, Furrow Wheel	1	1		1
13	353	616 X1	62-001-212	Bolt, Hex. Hd., Axle to Spindle to				
				Bracket (use on Double Locking Axle).	-	1	_	1
	353	433 X1	62-14	Washer, Lock	-	1	_	1
	353	568 X1	44-001-212	Bolt, Hex. Hd., Axle to Spindle to		1.3		
27				Bracket (use on Single Locking Axle).	-	1	-	1
	353	841 X1	44-011-288	Bolt, Carr. (Not Illustrated)	1	-	-	-
	353	772 X1	44-204	Washer, Flat (Not Illustrated)	1	124	-	_
	353	432 X1	44-14	Washer, Lock	1	1	-	-
	353	426 X1	44-003	Nut, Hex. (Not Illustrated)	1		-	-
	353	573 X1	44-001-275	Bolt, Hex. Hd., Axle to Spindle to		1		-
00	250	770 VI	44 004	Bracket	1	1	-	1
28		772 X1	44-204	Washer, Flat	-	1	-	. 1
		432 X1	44-14	Washer, Lock	1	1	-	1
	353	426 X1	44-003	Nut, Hex	1	1	118-134	1
29	660	155 M1	P-A0-3806-B	Bracket, Furrow Wheel Scraper	1	1	(F-) 03	-
30	660	156 M1	P-A0-3807-A	Scraper, Furrow Wheel	1	1	1 1 - 00	-
	353	827 X1	44-011-112	Bolt, Carr., Scraper to Bracket	2	2	-	-
31	353	757 X1	44-104	Washer, Flat	2	2	-	-
31	353	432 X1	44-14	Washer, Lock	2	2	-	=
	353	426 X1	44-003	Nut, Hex	2	2	-	-
						Acres 1	0- DEL 08	
32				Kit, Wheel Weight (tapped holes)	1	-	-	-
	353	706 X1	44-101-200	Screw, Cap	2	mate I	2 -	1 = I
	353	772 X1	44-204	Washer, Flat	2	-	-	-
33				Kit, Wheel Weight, Outside, For Plows w/ Light Wheel having drilled holes			100-10	12 1
				(Inc. Weight not serviced)	1	-	me on	-
	353	563 X1	44-001-150	Bolt, Hex. Hd. (Not Illustrated)	4	-	-	
		432 X1	44-14	Washer, Lock (Not Illustrated)	4	-	E- 10	-
		426 X1	44-003	Nut, Hex. (Not Illustrated)	4	-	-	-
34				Kit, Wheel Weight, Outside, For Plows w/ Heavy Wheel having tapped holes			500 ps	
				(Inc. Weight not serviced)	1	1	-	- 14
	353	699 X1	44-101-112	Screw, Cap	4	4	-	-
						The second secon		

F79 B



Ref.								No.		
No.		Par	t No		Replaces	Description	P-AO-20	P-A0-21	P-A0-98	P-AO-99
1	6	60	113	M1	P-A0-8024	Bracket, Spring, R.H	(1-22-327	04-2	1	1
2	6	60	114	M1	P-A0-8025	Bracket, Spring, L.H	-	nn-re	1	1
	ſ 3	53	568	X1	44-001-212	Bolt, Hex. Hd., Brackets to Spring	RECEIPT AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN TO ADDRESS OF THE PERSON NAMED IN COLUMN TO ADDRESS OF	0-14-1	1	1
3			432		44-14	Washer, Lock	-4 M	0-01-	1	1
J	1000		426		44-003	Nut, Hex	70	-	1	1
4	6	60	160	Ml	P-A0-8023	Spacer, Spring Bracket	-	-	1	1
5	6	60	159	Ml	P-A0-8021	Spring, Counterweight	0 =:= 13	1-0-	1	1
	16	:60	131	м1	P-A0-8022	Eyebolt, Turnbuckle	_	-	1	1
6	1		428	-	44-1003	Nut, Jam Hex	_	-	1	1
7	6	60	158	M1	P-A0-8033	Bracket, Turnbuckle	-		1	1
8	6	660	143	M1	P-AO-8031	Swivel, Turnbuckle	-	-	1	1
	11	95	411	м1	S-10214-S	Pin, Clevis, Bracket to Clevis	-	-	1	1
9	1 7		066	(SCHEET)	16-05-100	Pin, Cotter	-	-	1	1
10	6	660	157	Ml	P-A0-8026	Clevis, Counterweight Spring	-	-	1	1
	(1	105	353	мп	S-10215-F	Pin, Clevis, Clevis to Plow Strut	-	-	1	1
11	1.0		760		62-104	Washer, Flat	-	-	1	1
11			066		16-05-100	Pin, Cotter	-	-	1	1